



## Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

July 24, 2000

Department of Environmental Quality  
Division of Water Quality  
288 North 1460 West  
P.O. Box 144870  
Salt Lake City, Utah 84114-4870

Attention: Mr. Michael Herkimer

Subject: July 2000, UPDES Compliance Report  
June 2000, Monitoring Period  
UPDES Permit No. UT0024759  
Discharge Monitoring Report Forms  
Sunnyside Cogeneration Facility, Sunnyside, Utah

*Rusty Netz*  
*Incoming*  
*ACT/007/035*

Dear Mr. Herkimer:

This letter summarizes the UPDES-Permit field activities at the Sunnyside Cogeneration Facility during June 2000. Rusty Netz, the Environmental Coordinator for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the June 2000, monitoring period. Attached are the Discharge Monitoring Report Forms (EPA No. 3320-1).

If you have any questions concerning this report, please contact Rusty Netz at (435) 888-4476.

Sincerely,

Agent for  
Sunnyside Cogeneration Associates

Randy Scott  
Plant Manager

RN/ta  
Enclosures:

cc: Ken Wyatt, Division of Oil, Gas and Mining  
SCA Plant file  
Rusty Netz, COSI

*[Faint, illegible text]*